

Radon Testing Results - **Eola Hills Charter School**

Action Level is 4.0 pCi/L

Site Name	Building Name	Room Description (per floor plan)	Kit serial #	Date sampled	Type of test
Eola Hills Charter School	MODULAR	Mn Office	4947192	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	COM Office	4947158	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	COM Office	4958413	6/10/20	Blank
Eola Hills Charter School	MODULAR	COM Office	4947426	6/10/20	Duplicate
Eola Hills Charter School	MODULAR	Main Office	4947139	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	BLDG 2	4949417	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	BLDG 2	4949317	6/10/20	Duplicate
Eola Hills Charter School	MODULAR	BLDG 3 RT	4949499	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	BLDG 3 RT	4949287	6/10/20	Duplicate
Eola Hills Charter School	MODULAR	BLDG. 3 REAR	4947293	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	BLDG. 3 REAR	4958248	6/10/20	Duplicate
Eola Hills Charter School	MODULAR	BLDG. 3 REAR	4949345	6/10/20	Blank
Eola Hills Charter School	MODULAR	BLDG 4 REAR	4949293	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	BLDG 4 REAR	4949237	6/10/20	Duplicate
Eola Hills Charter School	MODULAR	BLDG 4 FRONT	4922445	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	BLDG 4 FRONT	4949514	6/10/20	Duplicate
Eola Hills Charter School	MODULAR	ROOM 5	4947272	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	ROOM 5	4949349	6/10/20	Duplicate
Eola Hills Charter School	MODULAR	ROOM 5 COMP	4949530	6/10/20	Detector Kit
Eola Hills Charter School	MODULAR	ROOM 5 COMP	4958342	6/10/20	Duplicate

Results (pCi/L)
0.3
0.2
0.2
0.3
0.2
0.3
0.2
0.2
0.2
0.2
0.2
0.2
0.2
0.5
0.4
0.6
0.3
0.2
0.3
0.3
0.2